




R.A.E.S. Calibration

TEMPERATURE CALIBRATION

The unit of measurement for temperature is called a DEGREE. It varies for the different temperature scales, When the scale extends below zero, values below zero are identified by a minus sign. Fahrenheit, Celsius, Centigrade are common units of measurement for Temperature.

At R.A.E.S. Calibration we calibrate all makes of instruments which deal with Temperature.

- Detailed Certificates
- Low Prices
- Quick Turn Around Time
- Automatic Recall
- Free Delivery (USA)
- Free Technical Assistance



Not limited to:

- Asten Instruments
- Dickson
- Digitec
- Dwyer
- Extech
- Fisher
- Fluke
- Hart Scientific
- Honeywell
- Omega
- Omron
- Raytek
- Rosemount
- Rueger
- Siemens
- Tel-Tru
- Tempcon
- Tenma
- Watlow
- Weiss Instruments
- WGTC

Calibrations are N.I.S.T. traceable & compliant to ANSI-540-1/NC SL Z540-1, MIL-STD-45662, ISO 17025, ISO 9000/2000



R.A.E.Services Inc.

CAGE Code: 3SGV9

Mailing Address

P.O. Box 4730
Glendale, CA 91222 USA

Phone: 1-866-FASTLAB

Fax: 818-686-0520

Email: info@raelectrical.com



www.raescalibration.com